# ALABAMA REGISTER OF LANDMARKS & HERITAGE NOMINATION FORM

Alabama Historical Commission 725 Monroe Street Montgomery, Alabama 36130

NOT FOR PUBLICATION

COUNTY

Calhoun

CONGRESSIONAL DISTRICT

CODE

#### SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES -- COMPLETE APPLICABLE SECTIONS

### 1 NAME

HISTORIC

STATE

Mallory-Scarbrough-Prather House AND/OR COMMON

# **2 LOCATION**

STREET & NUMBER Co. Hwy. 55, Imi. sw of Choccolocco Community CITY, TOWN

Anniston

CODE

X VICINITY OF

Alabama

## **3 CLASSIFICATION**

CATEGORY	OWNERSHIP	STATUS	PRES	ENTUSE
_DISTRICT	PUBLIC	SOCCUPIED	AGRICULTURE	MUSEUM
_3BUILDING(S)	X PRIVATE	UNOCCUPIED	COMMERCIAL	PARK
STRUCTURE SITE	-BOTH PUBLIC ACQUISITION	WORK IN PROGRESS	EDUCATIONAL	-RELIGIOUS
OBJECT	_IN PROCESS	YES: RESTRICTED	GOVERNMENT	SCIENTIFIC
	BEING CONSIDERED	XYES UNRESTRICTED	_INDUSTRIAL	_TRANSPORTATION
		NO	MILITARY	OTHER

## **4 OWNER OF PROPERTY**

NAME

Mr. and Mrs. Robert W. Prather, III

STREET & NUMBER Route 5 Box 654

CITY, TOWN

Anniston

VICINITY OF

STATE Alabama

## **5** LOCATION OF LEGAL DESCRIPTION

COURTHOUSE.

REGISTRY OF DEEDS, ETC. Calhoun County Courthouse

STREET & NUMBER

CITY. TOWN

Anniston

STATE Alabama

## **6 REPRESENTATION IN EXISTING SURVEYS**

TITLE


DATE

\_\_FEDERAL \_\_STATE \_\_COUNTY \_\_LOCAL

DEPOSITORY FOR SURVEY RECORDS

CITY, TOWN

STATE



CONDITION

\_\_EXCELLENT %GOOD \_\_FAIR \_\_DETERIORATED \_\_RUINS \_\_UNEXPOSED UNALTERED

XALTERED

CHECK ONE

\_XOR \_\_MO

\_XORIGINAL SITE \_\_MOVED DATE\_\_\_\_\_

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Mallory-Scarbrough-Prather House is a two-story frame building, basically T-shaped in plan, with a gabled roof. Lower story windows of the symmetrical facade are 9/9 double-hung sash while the upper story windows are 9/6 double-hung sash, and flank a central twotiered pedimented portico. Windows on both stories of the facade are flanked by narrow vertical sidelights, as is the double-leaf paneled main entrance and the single-leaf paneled door opening onto the portico balcony. Both doors are topped with transoms.

At an unspecified date, a rear dog trot running east to west was enclosed, and in 1976 a laundry room and bathrooms were built into the west end of the space. In 1979, a porch on the right of the rear wing was enclosed and a kitchen added.

# **8 SIGNIFICANCE**

SPECIFIC DAT	ES mid-1840's	BUILDER/ARCH	ITECT	
_1900-	COMMUNICATIONS	_INDUSTRY _INVENTION	POLITICS/GOVERNMENT	OTHER (SPECIFY)
1700-1799 -x1800-1899	ART COMMERCE	ENGINEERING EXPLORATION/SETTLEMENT	MUSIC PHILOSOPHY	THEATER TRANSPORTATION
_1600-1699	XARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN
_1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
1400-1499	ARCHEOLOGY-HISTORIC	CONSERVATION	_LAW	SCIENCE
_PREHISTOHIC	ARCHEULUGY-PREHISTORIC	COMMUNITY PLANNING	LANDSCAPE ARCHITECTURE	RELIGION
PERIOD	AF	REAS OF SIGNIFICANCE CH	IECK AND JUSTIFY BELOW	

STATEMENT OF SIGNIFICANCE

The exact date of the Mallory-Scarbrough-Prather House's construction is unknown, but 1844 tax records indicate that the property upon which the house sits was owned by J. William Mallory, for whom the house was built. Mallory was an early settler of the Choccolocco community, and was credited as being one of the founders of the Georgia-Pacific Railroad. Upon the 960 acres he owned, Mallory built a grist mill, a thread mill and a linen mill which supplied cloth to the Confederate Army.

The house was sold in 1877 to Absalom Scarbrough, in whose family it remained until 1947. In that year, the property was sold to D. L. Wakely, and in 1971 the current owners purchased the house.

# 9 MAJOR BIBLIOGRAPHICAL REFERENCES

Tax records 1850 census Abstract of title Newspaper articles Personal interviews

**10**GEOGRAPHICAL DATA

QUADRANGLE N	AME Choccoloca	5		QUADRANGL	E SCALE 1:24000
	III	RTHING		EASTING	NORTHING
			F	Lulu	Lili
GL_ L	ILI L	ILL	нЦ	L'L'II	Lililui
VERBAL BOUN	DARY DESCRIPTIO	N			
	2002-0.				1220217
LIST ALL	STATES AND COUN	TIES FOR PROPER	TIES OVERLAPPIN	NG STATE OR COU	NTY BOUNDARIES
STATE		CODE	COUNTY		CODE
	EPARED BY	CODE	COUNTY		CODE
FORM PR	EPARED BY				CODE
FORM PRI	EPARED BY and Mrs. Rober			DATE	CODE
FORM PRI				DATE 3/8	
FORM PR	and Mrs. Rober				32
FORM PRIMARE / TITLE Mr. a DRGANIZATION STREET & NUMBER ROUTE	and Mrs. Robert			3/8 TELEP 237	12 HONE 
FORM PRIMAME / TITLE Mr. a DRGANIZATION STREET & NUMBER ROUTE CITY OR TOWN	and Mrs. Robert			3/8 TELEP 237 STATE	32 HONE 
FORM PRIMARE / TITLE Mr. a DRGANIZATION STREET & NUMBER ROUTE CITY OR TOWN Annis	and Mrs. Robert a 5 Box 654 ston	t W. Prather,	III	3/8 TELEP 237 STATE	12 HONE 
FORM PRIMARE / TITLE Mr. a DRGANIZATION STREET & NUMBER ROUTE CITY OR TOWN Annis	and Mrs. Robert	t W. Prather,	III	3/8 TELEP 237 STATE	32 HONE 
FORM PRIMARE / TITLE Mr. a DRGANIZATION STREET & NUMBER ROUTE CITY OR TOWN Annis	and Mrs. Rober e 5 Box 654 ston A HISTORICAL CO	t W. Prather,	III	3/8 TELEP 237 STATE	32 HONE 
FOR ALABAMA	and Mrs. Rober e 5 Box 654 ston A HISTORICAL CO	t W. Prather,	III	3/8 TELEP 237 STATE	32 HONE 
FOR ALABAMA Staff Membe	and Mrs. Rober e 5 Box 654 ston A HISTORICAL CO	t W. Prather, MMISSION USE	III	3/8 TELEP 237 STATE ALS	32 HONE 



#### STATE OF ALABAMA

ALABAMA HISTORICAL COMMISSION 725 MONROE STREET MONTGOMERY, ALABAMA 36130 PHONE: 832-6621



ALABAMA REGISTER OF LANDMARKS AND HERITAGE Nomination Form

COUNTY Calhoun

NAME: Present Prather Home Histori	c Old Scarbrough Place
LOCATION: Street and Number Route #5 Box 654	(East from Anniston to Golden Spring
Town (Give directions if rural) Anniston, A	L left on Choccolocco Rd for 4 Miles right 2nd house on left of Harmony
*A MAP WITH THE LANDMARK MARKED MUST BE SUBMIT	TED WITH THIS FORM* Baptist Church)
CATEGORY: Building (x) Structure ( ) Object (	) Site ( ) District ( )
USE: Present Private Residence Histori	c Private Residence
OWNERSHIP: Public ( ) Private (x)	
Owner's Name Mr. and Mrs. Robert W. P	Prather III
Mailing Address Route #5 Box 654	
Anniston, Alabama 36201	L
INTEGRITY: Original Site (x) Moved () When?	
From where?	_ (Give details in significance.)
CONDITIONS: Excellent (x) Good () Fair ()	Ruins ( )
THREATS: No (x) Yes () By What?	
RESTORATION WORK: Being considered ( ) Underway (*	) Completed ( ) Not planned ( )
SURROUNDING ENVIRONMENT: Open land ( ${\tt x}$ ) Woodland ( High building density ( ) Residential ( ${\tt x}$ ) Rural ( ${\tt x}$	Commercial ( ) Industrial ( )
Acreage 18	

For all categories other than a district and object give a site plan with a North arrow. Show related buildings. Incl #1

For a district give a verbal boundary description and attach a sketch map of the district.

DESCRIPTION (Continued)

Roof Type: (Gable, Gambrel, Minsard, Flat, Hipped Combination) Hipped

Roof Covering: (Wood shingle, Asphalt, Tile, Metal, Slate) Asphalt over wood shingles Roof Trim: (Cornices, bargeboard, brackets, etc.) none

Porches: Front (type and description) concrete (1950)

Rear (type and description) none

Side (type and description) 20' X 8' concrete (1950)

Doors: Main entrance (location, description)Exact center lower front consisting of double doors (4'X 62') with six recessed panels on each surrounded by single row of 10" X 12 hand-drawn glass panes on either side, double row across top. Exact center upper front-door opening onto balcony is single door with same

window treatment as main entrance.

Windows: Types and number of each floor of facade Two windows lower floor front are 6 10"X12" panes high, 5 panes wide. Two windows upper floor front, same except 5 panes high, Glass is hand-drawn floor for sides and rear Upper floor 3 each side

2 rear-Same type as front. Lower floor, 2 each side, same type as front. (5 windows are standard type bathroom and kitchen windows).

Interior: Describe mantels, stairways, wainscoting, plasterwork and any unusual feature All interior work is very plain Colonial Style.

Six mantels are approximately 5 ft. wide, pine, with fluted columns. Two stairways are heart pine with hand carved rails, slender, square balusters. Floors are random width pine boards. Plasterwork is glass smooth (Walls and ceilings). Chair rails are plain, hand carved.

Other: Use this space to describe any additions, alterations, outbuildings or other features of the structure and its surroundings.

Over the years concrete porches have replaced wooden porches. Dogtrot running East to West has been enclosed. Kitchen and baths have been added.

A dug well housed in a lattice well house is approximately 25 ft. from SW corner of house.

An old barn is in close proximity to the house.

On an additional sheet make a sketch of the floor plan of the building, showing dimensions if possible. SEE INCLOSURE # 2 THIS IS NOT REOUIRED!

SIGNIFICANCE:

Why is this landmark significant? (x) associated with events, persons, or movements Local (x) State () National () (x) a good example of a type or style of structure other

Explain: (Briefly state why the above is true)

The Mallorys that built the house were pioneers of the Harmony Settlement (Choccolocco Valley.) The size and simplicity of house is typical of pre-Civil War homes of landowners.

Architect or Builder (Give name and biographies, if known)

Unknown (Mr. J. William Mallory, Owner)

Give a complete but concise history of the Landmark. Include information on important people and events associated with the landmark. (USE ADDITIONAL SHEETS IF NECESSARY)

SEE INCLOSURE # 3

State sources of information, giving full bibliographical data: Tax Records - 1850 Census(Calhoun County Public Library) Abstract of Title Personnel conversation Gene Scarbrough Jan 74. Personal letter to Mrs. Wakely from Lucy Scarbrough November 1953 Anniston Times (Now defunct) 1934-1940 Harmony Baptist Church Records Anniston Star (October 72) Harmony Cemetary Grave Markers DESCRIPTION: PHOTOCRAPHS OF THE LANDMARK MUST BE SUBMITTED WITH THIS FORM. SEE INCLOSURE # 4 Complete as directed below for each category.

BUILDING:

Number of stories 2 Foundation Brick Basement crawl space Wall Material: (Note changes from one floor or wing to another) (clapboard, brick, stone, wood shingle, board and batton, stucco over wood or brick, metal, logs)

clapboard

Structural System: (If known) Wood frame (x) Load-bearing masonry () Iron or Steel () DESCREPTION (Continued)

\* STRUCTURE: On a separate sheet of paper give a complete as possible verbal description of the structure. (See examples)

OBJECT: On a separate sheet of paper give a complete as possible verbal description of the object. (See examples)

- SITE: On a separate sheet of paper give the present description of the site and how the site is believed to have looked during its period of importance.
- DISTRICT: On a separate sheet of paper give a general description of the district. Also needed is a numbered list of the structures in the district corresponding to the sketch map. This listing should include a name for the structure, a date of construction, a brief description, a statement of why the structure is significant, if it is.

\* SEE INCLOSURE #5

\*A MAP WITH THE LANDMARK MARKED AND PHOTOGRAPHS MUST BE SUBMITTED WITH THIS FORM\*

SEE INCLOSURE # 6

Map: A U.S. Geological Survey Map is preferred, but if you are unable to obtain one a county highway map may be used.

Photographs: Black and white, glossy finish, 5 x 7, or 8 x 10, is preferred.

#### FORM PREPARED BY


Name <u>Be</u> Address	tty A. Prather (Mrs. Robert W.,III) Route #5 Box 654	Date <u>17 MARCH 1982</u> Telephone 237-1920
own	Anniston, Alabama 36201	
rganiza	tion	
Alaham	a Historical Commission use only	
	a Historical Commission use only	
	a Historical Commission use only MMLENTS:	

U. I.	. M. Kelerence	Zone	- Easting	- Northing	
Thematic	Category				
Added to	ALABAMA REGIST	TER			

NATIONAL REGISTER Potential

·1/16" = apprx. 1 ft


OWNER'S CONCEPT OF HOW HOUSE LOOKED BEFORE ALTERATIONS.



West

non

Lower Floor



North

393.


1

Upper Floor

191

FRONT

ALL HELL



INCI #2

South

Eas,

Mallory - Scarbrough - Bathur Hsc.

THE MALLORYS WERE AMONG THE EARLIEST SETTLERS OF CHOCCOLOCCO TO MAKE A SIGNIFICANT CONTRIBUTION TO THE AREA THAT WAS CALLED HARMONY SETTLEMENT.

MR. WILLIAM MALLORY WAS AN ENTERPRISING GENTLEMAN. HE WAS A FOUNDER OF THE GEORGIA-PACIFIC RAILROAD AND ALSO A FOUNDER OF THE HARMONY BAPTIST CHURCH (ORGANIZED APRIL 1838). MR. MALLORY AND S.K. BORDERS DONATED THE LAND FOR THE HARMONY BAPTIST CHURCH. A NEW CHURCH BUILDING IS ON THE ORIGINAL SITE TODAY.

ON HIS ESTATE OF 960 ACRES, MR. MALLORY BUILT A GRIST MILL, A THREAD MILL, AND A LINEN MILL. THE GRIST MILL IS PRESENTLY THE HOME OF CAPT. AND MRS. PERRY DOER, JR. THE LINEN MILL PRODUCED CLOTH THAT WAS USED BY THE CONFEDERATE ARMY AND SOLD FOR \$50 A BUNCH.

ACCORDING TO FOLKLORE - DURING THE CIVIL WAR A LT. OF THE UNION ARMY HAD ORDERS TO BURN THE GRIST MILL BUT THE MILLKEEPER REASONED WITH THE SOLDIER AND TOLD HIM THE PEOPLE OF THE COMMUNITY WOULD STARVE. BEING A COMPASSIONATE MAN, THE SOLDIER BURNED THE THREAD MILL AND THE LINEN MILL; HOWEVER, THE LOSS WAS NOT AS GREAT AS SUPPOSED AS THE MACHINERY HAD BEEN REMOVED TO MUNFORD, ALABAMA SOME TIME BEFORE.

WILLIAM JR., JAMES, AND JOHN MALLORY FOUGHT IN THE CIVIL WAR. JAMES RETURNED HOME AND DIED OF WAR WOUNDS, HE IS BURIED IN THE HARMONY CEMETERY. ALICE MALLORY (DAUGHTER) MARRIED DR. JOHN MARION FRANCIS DAVIS. DR. DAVIS WAS THE LEADING PHYSICIAN IN CHOCCOLOCCO. ALICE M. DAVIS ORGANIZED THE LADIES AID SOCIETY AT THE HARMONY BAPTIST CHURCH.

AFTER THE CHAOS OF THE CIVIL WAR, MR. MALLORY'S WIDOW AND FOUR SONS MOVED TO ARKANSAS.

IN 1877 THE HOUSE WAS SOLD TO ABSALOM AND HATTIE SCARBROUGH FOR \$6250. AFTER THEIR DEATHS IN 1924 THE HOUSE STAYED IN THE HANDS OF THEIR SON L.L. SCARBROUGH UNTIL 1947. (TOTAL OF 70 YEARS). L.L. SCARBROUGH WAS OWNER OF SCARBROUGH DRUG STORE IN DOWNTOWN ANNISTON.

THIS HOUSE WAS HOME TO MANY FAMILIES DURING THE DEPRESSION YEARS AND WAS HOME TO SOLDIERS FROM FORT MCCLELLAN DURING WORLD WAR II.

L.L. SCARBROUGH SOLD THE HOUSE TO D.L. AND CLARA WAKELY IN 1947. IN SEPTEMBER 1971 THE HOUSE WAS BOUGHT BY PRESENT OWNERS. (ROBERT W. AND BETTY PRATHER).

### HISTORY OF LANDMARK

CANNOT ASCERTAIN EXACT YEAR HOUSE WAS BUILT. HOWEVER, THE FOLLOWING FACTS TEND TO PUT THE TIME IN THE 1840'S.

FIRST ENTRY IN ABSTRACT OF TITLE INDICATES THIS LAND WAS RESERVED FOR IS-WAR-NEHODJO BY THE CREEK TREATY OF 1832.

THE NEXT ENTRY IS A DULY SWORN, SIGNED, AND DATED AFFIDAVIT THAT ATTESTS TO THE FACT THAT ALL RECORDS OF DEEDS, MORTGAGES, AND ADMINISTRATION OF ESTATES OF PROBATE OFFICE OF CALHOUN COUNTY WERE DESTROYED BY FIRE WHILE BEING TRANSPORTED FROM JACKSONVILLE, ALABAMA TO TALLADEGA, ALABAMA. FOR SAFEKEEPING IN 1865. (8 NOVEMBER 1917).

THIRD ENTRY IS TRANSFER OF TITLE FROM MALLORYS TO A.B. SCARBROUGH ON 15 DECEMBER 1874.

TAX RECORDS OF 1844 STATES THIS PROPERTY OWNED BY J. WILLIAM MALLORY OF CHOCCOLOCCO CONSISTED OF 960 ACRES.

CHURCH RECORDS SHOW PRESENT CHURCH BUILDING STANDS ON LAND DONATED BY J. WILLIAM MALLORY. THE HARMONY BAPTIST CHURCH HAS BEEN IN EXISTENCE SINCE 1842. THIS CHURCH IS LOCATED APPROXIMATELY & MILE FROM HOUSE.

1850 CENSUS LISTS J. WILLIAM MALLORY, HIS WIFE, ELIZA, AND 10 CHILDREN.

STATEMENT FROM MISS MATTIE RHODES (DECEASED) THAT HER MOTHER ATTENDED A WEDDING IN THIS HOUSE BEFORE HER MARRIAGE IN 1855.

\* \* \* \* \* \*

and # 3

#### DESCRIPTION OF HOUSE

HOUSE IS A LARGE, TWO-STORY, FRAME, FARMHOUSE BUILT ON COLONIAL STYLE.

FACADE FEATURES MAIN ENTRANCE OF FOUR-FOOT DOUBLE DOORS SURROUNDED BY HAND-DRAWN GLASS WINDOW PANES AND FLANKED BY FOUR SQUARE COLUMNS. COLUMNS ARE SEPERATED ON TOP LEVEL BY A BALCONY ENCLOSED WITH LATTICE. SINGLE DOOR OPENS ONTO BALCONY WITH SAME WINDOW TREATMENT AS MAIN ENTRANCE.

FOUR LARGE WINDOWS (CONSISTING OF 30 PANES EA.) ON FRONT ARE EQUI-DISTANCE FROM CENTER ( TWO UPPER FLOOR-TWO LOWER FLOOR). NARROW WINDOWS ON EACH SIDE OF HOUSE (CONSISTING OF 10 PANES) ARE ON EITHER SIDE OF THREE BRICK CHIMNEYS.

INTERIOR OF HOUSE IS VERY SIMPLE. IT CONSISTS OF SIX LARGE, SQUARE ROOMS AND THREE HALLS. (OR 9 ROOMS) EACH ROOM AND HALL IS FINISHED IN SMOOTH PLASTER WITH A PLAIN CHAIR RAIL. HOUSE HAS SIX FIREPLACES. EACH MANTEL IS 5 FT. WIDE, PINE, COLONIAL STYLE. UPSTAIRS FLOORS ARE RANDOM WIDTH PINE BOARDS. DOWNSTAIRS FLOORS HAVE DETERIORATED OVER THE YEARS AND HAVE BEEN TILED, CARPETED, ETC OVER PLYBOARD. THERE ARE TWO STAIRCASES, ONE IN ENTRANCE HALL AND OTHER IN LEFT FRONT ROOM. BOTH STAIRCASES ARE HEART PINE AND VERY PLAIN. (ORIGINALLY THE STAIRS IN ENTRANCE HALL WAS ONLY ACCESS TO RIGHT UPPLER FLOOR AND STAIRS IN LEFT FRONT ROOM, THE ONLY ACCESS TO LEFT UPPER FLOOR.

### ALTERATIONS

LA DOG TROT RUNNING EAST AND WEST HAS BEEN ENCLOSED. DATE UNKNOWN

ASPHALT ROOFING WAS PUT OVER WOODEN SHINGLES IN 1950.

CONCRETE PORCHES ON FRONT AND LEFT SIDE REAR ADDED IN 1950.

DOOR CUT THROUGH TO UPSTAIRS HALL IN 1971.

BATHS AND LAUNDRY ROOM BUILT INTO WEST END OF DOG TROT IN 1976.

PORCH ON RIGHT SIDE REAR ENCLOSED FOR KITCHEN IN 19/9.

ROOF LINE HAS NEVER BEEN CHANGED - NO MAJOR STRUCTURAL ADDITIONS.

Incl #5