

STATE OF ALABAMA

ALABAMA HISTORICAL COMMISSION  
725 MONROE STREET  
MONTGOMERY, ALABAMA 36130  
PHONE: 832-6621



ALABAMA INVENTORY AND WORKSHEET FOR LANDMARKS

COUNTY CLEBURNE

PRESENT NAME Heflin Depot HISTORIC NAME Southern Railway Depot

LOCATION (Street and number) 1001 Ross Street

TOWN (Give directions if rural) Heflin

PRESENT USE \_\_\_\_\_ HISTORIC USE \_\_\_\_\_

OWNERSHIP: Public ( ) Private (x) Public acquisition being considered ( )

OWNER'S NAME The Cleburne County Arts & Crafts League, Inc.

MAILING ADDRESS Box 393 1001 Ross Street

Heflin, Alabama

CONDITION: Excellent ( ) Good ( ) Fair (x) Ruins ( )

INTEGRITY: Original Site ( ) Moved (x) When? July, 1974

From where? \_\_\_\_\_ Give details in significance.

THREATS: No ( ) Yes (x) By What? Vandalism

RESTORATION WORK: Being considered (x) Underway ( ) Completed ( ) Not planned ( )

SURROUNDING ENVIRONMENT: Open land ( ) Woodland ( ) Scattered buildings ( )  
High building density ( ) Commercial ( ) Industrial ( )  
Residential ( ) Rural ( )

If there are numerous buildings in the area, could this structure be part of a Historic District?

SIGNIFICANCE: Why is this important (x) associated with events, persons, or movements  
Local ( ) State ( ) National ( )  
(x) a good example of a type or style of structure  
( ) other

Explain: (Expand on the significance of the building. If architecturally significant, give details being very specific. Additional data on what aspects of the community's development the building represents, or a specific event, trend or person related to the building's importance.)  
Typical turn-of-the-century depot, has played a vital role in the settlement and growth of the City of Heflin.

Date of Construction:  
Builder or Architect: (Give names and biographies, if known)

Original Owner: (Give name and biographies--attach additional sheet if necessary)

Subsequent Owners (Give name and biographies)

State sources of information, giving full bibliographical data:

SECTION III: DESCRIPTION (In each category please state if elements are not original)  
YOU MUST PROVIDE US WITH PHOTOGRAPHS OF THE STRUCTURE, SHOWING FRONT, SIDE, REAR  
AND NOTABLE DETAILS.

Number of stories \_\_\_\_\_ Foundation \_\_\_\_\_

Basement \_\_\_\_\_ Interior framing or structural system \_\_\_\_\_

---

Exterior wall material and design: (Note changes from one floor or wing to another)

Roof type and covering:

Roof Trim: (Cornices, vergeboard, brackets, etc.)

Chimneys: (Give number, location, and material)

Porches: Front (type and description) \_\_\_\_\_

Rear (type and description) \_\_\_\_\_

Side (type and description) \_\_\_\_\_

Doors: Main entrance (location, description)

Other entrances: (location, description)

Windows: (Give types, number for each floor of facade, describe trim)

(Give types, number per floor for rear and sides)

#### INTERIOR FEATURES

Mantels: (Number, location, and description):

Describe interior window and door trim:

Stairways (types, locations and features)

Wall and ceiling finish: (Include wainscotting, plasterwork, cornices, etc.)

Flooring: \_\_\_\_\_ Notable hardware: \_\_\_\_\_

General setting and orientation:

Outbuildings:

Give all alterations and additions: (Be specific, give date of change and original appearance when known)


Make a sketch of the floor plan of the building, showing dimensions, related structures, and additions. Also give north arrow and indicate front of the structure.

Form prepared by \_\_\_\_\_ Date \_\_\_\_\_

Address \_\_\_\_\_ Phone \_\_\_\_\_

Town \_\_\_\_\_

Organization \_\_\_\_\_



21

22

23

24

25

Cahulga

17

16

ALMON

PERRYMAN BRIDGE ROAD

15

14

Pumpkin Patch

STEWELL

SOUTHERN DR

9

8

HELIN

10

11

11

Helin

(BM 9777)

BELLSMITH

ROAD

11

11

11

HELIN

HELIN

HELIN

HELIN

HELIN

HELIN

4

3

2

1

HEALTH TRAINING SCHOOL

HEALTH TRAINING SCHOOL

HEALTH TRAINING SCHOOL

HEALTH TRAINING SCHOOL

BOZZE

BOZZE

BOZZE

BOZZE

BOZZE

BOZZE

BOZZE

BOZZE

NATIONAL FOREST

BOZZE

BOZZE

BOZZE

BOZZE