

RECEIVED

JUN 17 1991

Ala. Historical Commission

ALABAMA REGISTER OF LANDMARKS AND HERITAGE CRITERIA

Alabama Register Property Information

1. NAME

Historic - a. Ackerville Baptist Church of Christ
(1848 Deed at previous location)
b. Baptist Church at Ackerville
(1886 Deed at present location)

Note: See attached copies of both 1848 and 1886 Deeds.

Common - ACKERVILLE BAPTIST CHURCH

2. LOCATION

The Church is approximately 2 miles North of the Junction of Alabama State Highways 21 and 89 in Ackerville, Wilcox County, Alabama. It is some 17 miles East of Camden and 30 miles South of Selma.

NW 1/4 of the NE 1/4, Section 9, Township 12, Range 10.

3. CLASSIFICATION

Category - Building Ownership - Private
Status - unoccupied Accessible - 2nd Sun. Oct. ONLY
Present Use - educational and religious

4. OWNERSHIP OF PROPERTY

Stuart Family Reunion
(aka Ackerville Baptist Memorial Association)

History Committee Chairman - (205)661-8976
James A. Stuart
4081 Lancewood Drive
Mobile, Alabama 36609


Treasurer

Anita S. Clink (205)666-1170
669 Tarawa
Mobile, Alabama 36609


5. FLOOR/SITE PLAN

Ackerville Baptist Church
Wilcox County
Ackerville, Alabama

May 15, 1991



Alabama State Highway 89



6. DESCRIPTION Ackerville Baptist Church
Wilcox County
Ackerville, Alabama

A. Condition - Fair

B. Altered - Prefabricated concrete steps to front porch added circa 1960. The brick chimney on the roof originally served a pot-bellied stove and stove pipes inside which are no longer present. At some time a galvanized tin roof — replaced the original material (wooden shakes?). The 4 square columns on the front, when replaced, were identical to the originals. The red brick foundation piers were replaced in 1988. Brace rods have been installed from side to side to prevent the foundation from spreading apart.

C. Moved -

1. Ackerville Baptist Church was moved to the present site beginning in 1879 and was completed on site in August, 1881.
2. Please refer to property deed of 1848. No specific location is given although it has always been referred to as Ackerville Baptist Church.
3. The original location was Oak Hill, known today as "Old Oak Hill." This is approximately 3/4 mile north of the present location.
4. The Church was taken apart, piece by piece, and taken by mules and wagons to the present site where it was re-assembled in its design. Provisions were made for a cemetery to the rear of the building which is still intact. The cemetery at the old site was not disturbed.
5. Unknown.
6. The Church was moved to be closer to the then-thriving community, which included Dr. Stabler's office, U.S. Post Office, cotton gin/grist mill, sawmill, grocery store, blacksmith shop and school -- all within 1/4 mile. The move was initiated by George W. Stuart, his brothers James Allen and William, and their neighbors.

D. Written Description

ACKERVILLE BAPTIST CHURCH
WILCOX COUNTY
ACKERVILLE, ALABAMA

1.) Ackerville Baptist Church is a single story structure, 42'x27' 2.) with free-standing clay brick piers 18-20 inches in height, with no underpinning or ventilators. 3.) The large framing timbers are original although from the outside it is not evident whether it is mortise and tenon. This building was first constructed in 1848. 5.) The exterior wooden clapboard walls are painted white and made of true 1"x6" hand-hewn lumber. 6.&7.) There is a triangular gable over the front porch, which is supported by 4 square wooden columns, 12" wide on each side. The flooring is 1"x5" tongue and groove boarding. The porch is 23'x7' and does not extend beyond the gable. Originally, wooden steps to the porch ran across the entire width of the porch but pre-fabricated cement steps with side metal rails are presently used between the 2 center posts 8.) On the front, there are two sets of wooden double-doors, opening inward, and a single wooden door on the north side, which also opens inward. There are 4 windows on the south wall, 3 on the north wall and 2 on the west wall behind the pulpit area. Originally, there were wooden louvered shutters, painted dark green, which could be shut over the windows.

9. & 10.) The roof is hipped and is presently covered in galvanized tin, with no trim. 11.) The old clay brick chimney comes through the pitch of the roof some 20' in from the west wall. It is now capped-off having once served a pot-bellied stove in front of the pulpit.

12.) The main entrance consists of 2 sets of wooden double doors on the front porch. Over each entrance is a 2-pane fixed transom. There is simple wooden framing around the door facings. The other doorway on the north wall is also a Christian panel wooden door with simple trim on the door facing and 4 wooden steps to the outside. 13.) There are no windows on the front of the building. All 9 windows, as described above, are single-hung, 9 over 9 with poured glass, 80"x36". Simple framing trim is used on the outside. 14.) All doorways and windows are framed inside with true 1"x6" trim. Inside the building, there are no stairways, chair-rails, baseboards, wainscotting, plasterwork or cornices. Interior walls and the ceiling are of hand-hewn 1"x6" boarding butted, "sealed", together using some blacksmith-made square head tapered nails. The flooring uses the same materials and method. All surfaces are painted.

15. The original lighting consisted of a 6 light oil burning chandelier which was hung from the center of the ceiling. Matching oil burning wall sconces, some 8-10, were placed between the windows along the outside walls. These sconces all gradually disappeared by the early 1950s. The chandelier was stolen in the late 1960s. Rumor has it that a local congregation relieved the chandelier from its original church and still has it. The locks, showing an 1879 patent, are the standard 4" square surface-mounted type used with a turnkey. Butt hinges are used throughout. There is no heating system in the building at present as the pot-bellied stove was removed in the early 1950s. 16. There have been no additions to the original building. Alterations include using a tin roof, adding prefabricated concrete steps to the front porch and brace rods installed from side to side to secure the wooden floor sill. (See 6.B.)

17. From State Highway 89, the unpaved driveway dips slightly and rises again to a knoll. The church, which faces the highway, sits on this knoll with the fenced cemetery behind the structure. The church faces eastward. The land slopes gently to small ravines on both the right and left sides of the church yet it remains level well past the cemetery to the west. On the left side are 4 very large red oak trees, apparently planted in a straight line. A one-room school house once sat to the right of the driveway as it starts up the knoll. The children used the church-yard during recess. The schoolhouse, demolished in 1942, was never owned by the church. The Family has the grounds and the cemetery mowed 2-3 times a year. 18. No Outbuildings.

7. SIGNIFICANCE

A. Period 1800-1899.

B. Areas of Significance

Architecture

Education

Religion

Social

C. & D. Specific Dates and Builders

1848 Original construction. Builders: unknown.

1881 Move to the present site completed by church members.

E. Statement of Significance

1. Ackerville Baptist Church is an example of building design and construction methods circa 1850 in the rural areas of Wilcox County, Alabama. All the original lumber was locally milled and obviously hand-hewn in places. The building was taken down, moved to the present site and carefully reconstructed. Once completed it continued to serve as a religious, and social center of the small, then-flourishing, community of Ackerville. A schoolhouse for the children of the area was also built on this site, although it was not owned by the church. The existence of this church is indicative of the role religion held in the lives of the early settlers. It was built in 1848 and was served by circuit riding ministers at times. Eventually there was a pastor, a bustling Sunday School and picnics on the grounds. Nearly 150 years later, members of our extended family have been attending annual Family Reunions since 1936, and we still have dinner on the grounds on the second Sunday in October. Ackerville Baptist Church was the focal point of the community in the past and is the only building, other than a few private homes, still standing in Ackerville. Our family still cherishes the ties that bind us to our ancestors as embodied by this little country church.

2. According to the land deed of 1848, on file at the Wilcox County Courthouse, property was given by a family specifically for the purpose of erecting the Ackerville Baptist Church of Christ. It was later decided by George W. Stuart, his brothers James A. Stuart and William A. J. Stuart and their friends and neighbors to move the entire structure to the present site about 3/4 mile south, to better serve the community growing at the crossroads. This task was completed in August, 1881. The materials had been hauled by mules and wagons. According to the deed, the land was purchased from the Lang/Holt family in 1886. A one-room schoolhouse once shared the 3 acre lot with the church building and the area that would become the cemetery directly behind the church. During this time, a U. S. Post Office, Dr. Stabler's office, a grocery store, sawmill, and a cotton gin were all located just south of the crossroads on State Highway #89 and an old unpaved road to Snowhill.

By 1900, however, the population began to decrease as young people moved into the cities, such as Selma, Montgomery, Birmingham, Bay Minette, and Camden. Others moved on to hopefully better farmland. William A. J. Stuart was in charge of Church Affairs at the church until his death in 1923. The Church continued to be used for regular services and functions into the 1930s. The first Annual Stuart Family Reunion or Ackerville Homecoming was organized by Dr. Whit W. Stuart, at the request of his father, George W. Stuart. It was held on a Sunday in early September, 1935, with some 150 in attendance. Events of the day were recorded in the

Willcox Progressive Era for all to read. Annual Reunions resumed after World War II, on the second Sunday in August.

By 1940, there was no longer a functioning congregation; since then there have been only occasional funerals and/or burials in the cemetery. As long as there is at least one annual meeting in the church, the family retains ownership.

The Ackerville Baptist Memorial Association was established in the mid-1950s to care for the cemetery and grounds. The church itself was eventually added to this concern. In 1988, the Reunion was first held on the second Sunday in October in order to encourage attendance. Overall, there have been only minor physical changes such as, concrete steps, replaced front columns and foundation piers, and the removal of the pot-bellied stove. Today, there is no heating, running water or electricity.

3. There is a standing Building Committee which was authorized, in October, 1990, to replace falling foundation sills and areas of weakened flooring. The family wants to channel more funds, when available from the Memorial Association into repairs and upkeep of the church rather than to just the cemetery and grounds. Lack of electricity on site does make it more difficult to find workmen who will come to the site for repairs. Another difficulty is that most of the interested family members live at some distance from the church. Declining attendance and/or interest is also a distressing problem.

8. MAJOR BIBLIOGRAPHICAL REFERENCES

There may be some articles of interest in old editions of the Willcox Progressive Era, as mentioned above but, for the most part, this information is as I remember hearing older relatives recount the events, and the things I have seen. Both property deeds are on file in the Willcox County Courthouse.

9. GEOGRAPHICAL DATA

A. 3 acres

B.

C. Commencing at a point 190 yards South of the NE corner of the NW 1/4 of NE 1/4 Section 9, Township 12, Range 10, thence West 180 yards, thence South $80 \frac{2}{3}$ yards, thence East 180 yards, thence North $80 \frac{2}{3}$ yards to said starting point, and containing 3 acres. All of said lines running at the same degree of the original land lines.

10. FORM PREPARED BY

James A. Stuart

Stuart Family Reunion

4081 Lancewood Drive, South

Mobile, Alabama 36609

May 15, 1991

(205) 661-8976

11. COLOR SLIDES OF PROPERTY

Please see enclosed.

DEED OF ACKERVILLE BAPTIST CHURCH
AS RECORDED IN
WILCOX COUNTY COURTHOUSE,
CAMDEN, ALABAMA
Records Looked Up By
John Allen Stuart
July 1, 1963

Deed Book J page 55

Jesse Smith and wife
Katherine Smith

Date of Deed: July 22, 1848

Date of Record: July 24, 1848

To

John Colly, I.C. Jones,
and I.C. Kirven, and their
Successors in office, as
Deacons of the Ackerville
Baptist Church of Christ,
In Trust and for exclusive
use of the same so long as
said Church remains in
existence.

Consideration: Love and re-
spect I bear unto the Gospel
of our Lord and Savior Jesus
Christ and the religious
benefit of the people and
citizens.

Description of Property Conveyed:

Two acres of land in said County for the purpose of erecting
a meeting house thereon and a graveyard should it be thought
necessary so much of which should be held sacred forever.

Beginning at an oak tree opposite the new school house near
and on the East side of the public road running Northerly
parallel with the said public road 140 yards, thence
Westerly 20 yards, thence Southerly 140 yards, thence
Easterly to the beginning point.

The same I do hereby warrant and forever defend for the
purpose above stated from by heirs and all other persons
pretending to claim same.

Recites: "In trust and for the exclusive use of the same so
long as the said Church remains in existence."

NOTE: No Section Township or Range is shown in the above
description.

DEED OF ACKERVILLE BAPTIST CHURCH
AS RECORDED IN
WILCOX COUNTY COURTHOUSE,
CAMDEN, ALABAMA
Records Looked Up By
John Allen Stuart
July 1, 1963

Deed Book W page 466

Warranty Deed of

Date of Deed: Jan. 23, 1886

Date of Record: Feb. 9, 1886

J.B. Lang, B.H. Lang,
D.M. Lang, M. F.Lang,
Serena C. Lang, W.L. Holt,
Pettle S. Boykin, J.W. Holt,
S. W. Lang, R.B. Lang, Kenan
C. Holt

Consideration: \$15.00

To

Baptist Church at Ackerville

Description of Property Conveyed:

Commencing at a point 190 yards South of the NE corner of the NW 1/4 Section 9, Township 12, Range 10, thence West 180 yards, thence South 80 2/3 yards, thence East 180 yards, thence North 80 2/3 yards to said starting point, and containing 3 acres. All of said lines running at the same degree of the original land lines.

Color Slides of Ackerville Baptist Church
April, 1991

During processing it appears that some of the slides have been mounted incorrectly -- in the reverse. Labeling on each slide has been done to show the correct view.

- #1 View of Ackerville Baptist Church from State Highway #89
- #2 4 large oak trees to the left of the Church
- #3 Front of the church - exterior east wall
- #4 Front of the church - exterior east wall
- #5 Exterior north wall
- #6 Exterior west wall
- #7 Exterior south wall
- #8 Ackerville Baptist Cemetery west side of church
- #9 1 of 2 sets of double doors front entrance east exterior
- #10 Interior - lock set and porcelain door knob front doors
- #11 Original pews and pulpit as seen from front door
- #12 Single door on north wall
- #13 Interior seen from pulpit looking east to front doors
- #14 Looking east to highway - site of old school under
under trees on left

ALABAMA SURVEY FORM

IDENTIFICATION

STRUCTURE NUMBER: _____

PHOTOGRAPH NUMBER: ROLL _____ NEGATIVE _____

ROLL _____ NEGATIVE _____

COUNTY NAME: Wilcox

HISTORIC NAME: Ackerlyle Baptist Church of Christ

COMMON NAME: _____

LOCATION

STREET NUMBER: _____

STREET NAME: Alabama State Highway 89

CROSS STREET: _____ DIRECTION: _____

NEAREST TOWN: Ackerlyle

PROXIMITY TO TOWN: _____ ZIP CODE: _____

- Unknown
- Within town limits
- Within 1 mile
- 1 to 5 miles
- 5 or more miles
- Other:

SECTION/TOWNSHIP/RANGE: 9 - 12 - 10

UTMs EASTING: _____

NORTHING: _____

QUADRANGLE SHEET: _____ SERIES: _____

TAX MAP NUMBER: _____

ORIENTATION: Unknown N S E W NE NW SE SW Other:

CATEGORY/USE/CONDITION

- TYPE:
- Unknown
 - Building
 - Structure
 - Site
 - Object
 - Other:

USE

ORIGINAL (PRIMARY)

. ORIGINAL (SECONDARY)

. . PRESENT

. . .
1 2 3

----- Unknown ----- Vacant/Not in use
----- N/A ----- Other:

[DOMESTIC]

- Camp
- Hotel
- Institutional housing
- Multiple dwelling
- Residence - non farm
- Residence - farm
- Secondary structure
- Village site

[COMMERCE/TRADE]

- Bank
- Business office
- Department store
- Office - unspecified
- Organizational office
- Professional office
- Restaurant
- Store - unspecified
- Specialty store
- Trade
- Warehouse

[SOCIAL]

- Civic
- Clubhouse
- Meeting hall

[GOVERNMENT]

- City hall
- Capitol
- Correctional facility
- Courthouse
- Custom house
- Diplomatic building
- Fire station
- Government office
- Post office
- Public works

[EDUCATION]

- College
- Education related housing
- Library
- Research facility
- School

[RELIGION]

- Church
- Camp meeting/Retreat
- Ceremonial site
- Church - education facility
- Church - related residence
- Synagogue

[FUNERARY]

- Cemetery
- Grave/Burials
- Mortuary

[RECREATION/CULTURE]

- Auditorium
- Fair
- Museum
- Monument/Marker
- Music facility
- Outdoor recreation
- Resort
- Sports facility
- Theater
- Work of art

[AGRICULTURE]

- Agricultural outbuilding
- Agricultural field
- Animal facility
- Fishing/Horticultural facility
- Irrigation facility
- Processing
- Storage

[INDUSTRY]

- Communications facility
- Energy facility
- Extractive facility
- Manufacturing facility
- Processing site
- Waterworks

[HEALTH CARE]

- Clinic
- Hospital
- Medical office
- Resort
- Sanitarium

[DEFENSE]

- Air facility
- Arms storage
- Battle site
- Coast Guard facility
- Fortification
- Military facility
- Navy facility

[LANDSCAPE]

- Forest
- Garden
- Park
- Parking lot
- Plaza
- Street furniture/object
- Underwater
- Unoccupied land

[TRANSPORTATION]

- Air related
- Pedestrian related
- Rail related
- Road related
- Water related

CONDITION:

- Unknown
- N/A
- Excellent
- Good
- Fair
- Deteriorated
- Ruin
- Other:

SITE INTEGRITY:

- Unknown
- N/A
- Original site
- Structure moved
- Other:

YEAR MOVED: 1881

THREATS:

- Unknown
- N/A
- Abandonment
- Development - Public
- Development - Private
- Other:

DESCRIPTION - EXTERIOR STYLE

STYLE DEVELOPMENT:

- Unknown
- N/A
- High style
- Local execution of style
- Common form with stylistic details
- Common form with no stylistic details

STYLE GROUP: (Select up to 3 in order of predominance)

- First
 . Second
 . . Third
 . . .
 1 2 3
 Unknown
 No Style

[COLONIAL]

- Georgian

[EARLY REPUBLIC]

- Early Classical Revival
- Federal
- Federal/Greek Revival

[Mid-19 CENTURY REVIVALS]

- Gothic Revival
- Greek Revival
- Greek Revival/Italianate
- Italianate
- Octagon

[LATE VICTORIAN]

- Gothic - Victorian
- Italianate - Victorian
- Miscellaneous Victorian
- Queen Anne
- Queen Anne/Colonial Revival
- Renaissance Revival
- Romanesque
- Second Empire
- Shingle style
- Stick style

[LATE 19TH & 20TH CENTURY REVIVALS]

- Beaux Arts
- Colonial Revival
- Dutch Colonial Revival
- French Renaissance
- Mission/Spanish Revival
- Neo-Classical Revival
- Tudor Revival

[LATE 19TH & 20TH CENTURY AMERICAN]

- Chicago style
- Commercial style
- Craftsman
- Post WW II Colonial
- Prairie School
- Skyscraper

[MODERN]

- Art Deco
- International style
- Modern

Other: 19th century vernacular

DESCRIPTION - EXTERIOR FORM

COMMON RESIDENTIAL FORM:

- Unknown
- N/A
- Bungalow
- Colonial form
- Creole cottage
- Cumberland cottage
- Dogtrot
- Dogtrot - enclosed
- Double pen
- Extended I-House
- Foursquare
- I-House
- I-House with ell
- L-cottage
- Pyramidal roof
- Raised cottage
- Ranch
- Saddlebag
- Side gable w/recessed porch
- Shotgun
- Single pen - rectangular
- Single pen - square
- Spraddle roof
- T-cottage
- Tidewater cottage
- Other:

NON RESIDENTIAL FORM:

- Unknown
- N/A
- [COMMERCIAL]
- Free standing - gable front
- Free standing - parapet front
- Free standing - flat roof
- One story commercial block
- Multiple story commercial block
- Stacked vertical block
- [RELIGIOUS]
- Front gable - no steeple
- Front gable - center steeple
- Front gable - side steeple
- Front gable - central tower
- Front gable - side tower
- Front gable - twin towers
- Cross gable - tower in ell
- Rotunda
- Other:

NOTES:

DESCRIPTION - GENERAL EXTERIOR

OVERALL SHAPE:

- Unknown
- N/A
- Circular
- Cross-shaped
- Irregular
- Polygonal
- Rectangular
- Rectangular with ell
- Square
- H-shaped
- L-shaped
- T-shaped
- U-shaped
- Other:

INTERNAL PLAN:

- Unknown
- N/A
- One room
- Two rooms
- Hall and Parlor
- Linear plan
- Massed plan
- Side hall
- Central hall
- Central hall w/side hall
- Cross hall
- T-hall
- Other:

FACADE:

- Unknown
- N/A
- Asymmetrical
- Symmetrical

DEPTH:

- Unknown
- N/A
- 1 room
- 2 rooms
- 3 or more rooms
- Other:

OVERALL DIMENSIONS:

WIDTH: 27'4" DEPTH: 42'

HEIGHT:

- Unknown
- N/A
- 1 story
- 1 1/2 stories
- 2 stories
- 2 1/2 stories
- 3 stories
- 3 1/2 stories
- 4 or more stories
- Skyscraper
- Other:

FOUNDATION/BASEMENT:

- Unknown
- N/A
- Continuous foundation
- Partially underground basement
- Piers
- Piers with infill
- Raised basement
- Slab
- Underground basement
- Other:

FOUNDATION MATERIAL:

- Unknown
- N/A
- Brick
- Concrete
- Metal
- Stone
- Wood
- Other:

SKETCH PLAN:

DESCRIPTION - ROOF

MAIN ROOF CONFIGURATION:

- Unknown
- N/A
- [GABLE]
- Belcast gable
- Catslide roof
- Clipped gable
- Cross gable
- Front-orientated gable
- Hip on gable
- Multiple gables
- Parapet gable
- Pedimented gable
- Saltbox roof
- Side-orientated gable
- Spraddle roof
- Stepped gable
- [HIP]
- Belcast hip
- Gable on hip
- Hip
- Hip with cross gables
- Hip with double front gables
- Hip with triple front gables
- Pyramidal roof
- Truncated hip
- [OTHER ROOF CONFIGURATIONS]
- Flat
- Gambrel
- Mansard
- Monitor
- Parapet
- Sawtooth
- Shed
- Vaulted
- Other:

ROOF PITCH:

- Unknown
- N/A
- Low pitch
- Medium pitch
- High pitch
- Other:

FEATURES: (Select up to 4)

- Unknown
- N/A
- Belfry
- Belvedere/Openwalk/Widow`s walk
- Clock Tower
- Cresting/Lightening rod
- Cupola/Lantern
- Decorative dormer
- Decorative gable
- Dormer
- Steeple/Spire/Fletch
- Tower/Turret
- Wall dormer
- Other:

ROOF MATERIAL:

- Unknown
- N/A
- Asphalt shingle
- Ceramic material
- Corrugated metal
- Shake shingle
- Slate shingle
- Standing seam metal
- Tin shingle
- Wood shingle
- Other:

WALL CONSTRUCTION:

- Primary
- Secondary
-
- 1 2
- Unknown
- N/A
- Ballon frame
- Box frame
- Brace frame
- Load bearing masonry
- Log
- Metal truss
- Plank frame
- Platform frame
- Poured/Reinforced concrete
- Steel frame
- Timber frame
- Timber frame with infill
- Wood truss
- Other:

DESCRIPTION - EXTERIOR WALL MATERIAL

ORIGINAL:

Primary	Secondary		
:	:		
1	2		
<input type="checkbox"/>	<input type="checkbox"/>	Unknown	
<input type="checkbox"/>	<input type="checkbox"/>	N/A	
			[LOG]
<input checked="" type="checkbox"/>	<input type="checkbox"/>	[WOOD]	<input type="checkbox"/> <input type="checkbox"/> Diamond notch
<input type="checkbox"/>	<input type="checkbox"/>	Plain weatherboard	<input type="checkbox"/> <input type="checkbox"/> Full dovetail
<input type="checkbox"/>	<input type="checkbox"/>	Beaded weatherboard	<input type="checkbox"/> <input type="checkbox"/> Half dovetail
<input type="checkbox"/>	<input type="checkbox"/>	Drop siding/Novelty siding	<input type="checkbox"/> <input type="checkbox"/> Saddle notch
<input type="checkbox"/>	<input type="checkbox"/>	Flush board	<input type="checkbox"/> <input type="checkbox"/> Square notch
<input type="checkbox"/>	<input type="checkbox"/>	Vertical board	<input type="checkbox"/> <input type="checkbox"/> V-notch
<input type="checkbox"/>	<input type="checkbox"/>	Board and Batten	<input type="checkbox"/> <input type="checkbox"/> Log - unknown notching
<input type="checkbox"/>	<input type="checkbox"/>	Wood shingle	
<input type="checkbox"/>	<input type="checkbox"/>	Half-timbering	[METAL]
<input type="checkbox"/>	<input type="checkbox"/>	Bark	<input type="checkbox"/> <input type="checkbox"/> Cast iron
			<input type="checkbox"/> <input type="checkbox"/> Corrugated metal
			<input type="checkbox"/> <input type="checkbox"/> Pressed tin
		[BRICK]	
<input type="checkbox"/>	<input type="checkbox"/>	Brick - common bond	[CERAMIC]
<input type="checkbox"/>	<input type="checkbox"/>	Brick - English bond	<input type="checkbox"/> <input type="checkbox"/> Glazed terra cotta
<input type="checkbox"/>	<input type="checkbox"/>	Brick - Flemish bond	<input type="checkbox"/> <input type="checkbox"/> Terra cotta
<input type="checkbox"/>	<input type="checkbox"/>	Brick - mixed bond	<input type="checkbox"/> <input type="checkbox"/> Tile
<input type="checkbox"/>	<input type="checkbox"/>	Brick - Veneer	
<input type="checkbox"/>	<input type="checkbox"/>	Brick - undetermined bond	[CONCRETE]
<input type="checkbox"/>	<input type="checkbox"/>	Diaper work	<input type="checkbox"/> <input type="checkbox"/> Concrete/Cinder block
<input type="checkbox"/>	<input type="checkbox"/>	Glazed headers	<input type="checkbox"/> <input type="checkbox"/> Poured/Reinforced concrete
		[STONE]	
<input type="checkbox"/>	<input type="checkbox"/>	Stone - rubble	[GLASS]
<input type="checkbox"/>	<input type="checkbox"/>	Stone - cut	<input type="checkbox"/> <input type="checkbox"/> Glass block
			<input type="checkbox"/> <input type="checkbox"/> Glass curtain wall
			<input type="checkbox"/> <input type="checkbox"/> Pigmented glass
		[STUCCO]	
<input type="checkbox"/>	<input type="checkbox"/>	Stucco over brick	[SYNTHETIC]
<input type="checkbox"/>	<input type="checkbox"/>	Stucco over frame	<input type="checkbox"/> <input type="checkbox"/> Asbestos
<input type="checkbox"/>	<input type="checkbox"/>	Stucco over stone	<input type="checkbox"/> <input type="checkbox"/> Asphalt
<input type="checkbox"/>	<input type="checkbox"/>	Stucco over unknown frame	
			<input type="checkbox"/> <input type="checkbox"/> Other:

REPLACEMENT:

- Unknown
- N/A
- Aluminum siding
- Asbestos siding
- Asphalt siding
- Brick veneer
- Permastone
- Stone veneer
- Similar to original
- Vinyl siding
- Weatherboard
- Other:

DESCRIPTION - PORCH

PRINCIPAL PORCH INTEGRITY:

- Unknown
- N/A
- Altered porch
- Not original but historic
- Not original - modern
- Original porch
- Reconstructed porch
- Removed or fallen porch
- Other:

PRINCIPAL PORCH TYPE:

- Unknown
- N/A
- Attached porch
- Inset/Loggia porch
- Recessed porch
- Stoop
- Other:

PRINCIPAL PORCH HEIGHT:

- Unknown
- N/A
- 1 story
- 1 story with deck
- 2 or more stories
- 2 or more with tiers
- Multiple height
- Other:

PRINCIPAL PORCH WIDTH:

- Unknown
- N/A
- Entrance bay only
- Full facade
- More than 1 bay/not full
- Wrap around porch
- Other:

PRINCIPAL PORCH ROOF CONFIGURATION:

- Unknown
- N/A
- Engaged
- Flat roof
- Flat roof with deck
- Gable roof
- Hip roof
- Pedimented gable
- Shed roof
- Other:

PORCH DETAIL: (Select up to 3)

- Unknown
- N/A
- Arches
- Battered columns
- Bungalow porch
- Carolina porch
- Chamfered posts
- Classical details
- Decorative iron
- Enclosed end bay
- Flush boards on facade
- Piers
- Pilasters/Engaged columns
- Porch room(s)
- Pressed tin ceiling
- Rain porch
- Rustic posts
- Sawwork trim
- Turned posts/trim
- Other:

NOTES:

DESCRIPTION - CHIMNEYS

MAIN BLOCK CHIMNEYS:

N/A 1 2 3 4 more than 4

ORIGINAL CHIMNEY: NO YES

CHIMNEY PLACEMENT:

- Unknown
- N/A
- Exterior end
- Exterior front/rear
- Interior
- Interior end
- Interior end/exposed face
- Other:

CHIMNEY MATERIAL: (Select up to 2)

- Unknown
- N/A
- Brick
- Mud and stick
- Stone with brick stack
- Stone - cut
- Stone - rubble
- Stucco
- Other:

CHIMNEY DETAILS: (select up to 4)

- Unknown
- N/A

[DECORATIVE DETAILS]

- Chimney pots
- Common bond
- Decorative caps
- Diaper work
- Flemish bond
- Flue
- Glazed headers
- Mixed bond
- Other patterned brickwork
- Painted/Scored stucco
- Paneled stacks

[SHOULDER DETAILS]

- Double shoulders
- Single shoulders
- Sloped shoulders
- Stepped shoulders
- Tumbled shoulders
- Concave shoulders

[STACK PLACEMENT]

- Flush stack
- Free standing stack
- Centered stack
- Off-centered stack

Other details:

DESCRIPTION - DOOR/WINDOWS

NOTABLE DETAILING: NO YES

DESCRIPTION:

GENERAL EXTERIOR DESCRIPTION:

DESCRIPTION - INTERIOR

SPECIAL INTERIOR FEATURES: (Select up to 6)

Unknown
 N/A

[WALLS/CEILINGS]

- Beaded board
- Exposed construction material
- Fully paneled interior
- Marbleizing
- Modern Replacement
- Narrow flush boards
- Notable glass
- Notable hardware
- Notable plaster
- Notable woodwork
- Painted wood
- Paneled wainscot
- Pressed tin
- Stenciling
- Tongue and groove
- Wide flush boards
- Wood graining

[STAIRS]

- Curved stairs
- Double stairs
- Enclosed stairs
- Reversed stairs
- Spiral stairs
- Straight stairs
- Closed stringer
- Open stringer

[MANTEL]

- Notable mantel
- Overmantel
- Other:

GENERAL INTERIOR DESCRIPTION:

DESCRIPTION - PROPERTY

ACREAGE:

- Unknown
- N/A
- City lot/Less than 1 acre
- 1 to 10 acres
- 10 to 50 acres
- More than 50 acres
- Other:

SETTING:

- Unknown
- Rural - undisturbed
- Rural - built up
- Small town
- Urban
- Other:

OUTBUILDINGS/SUPPORT: (Up to 6)

- Unknown
- N/A
- Animal pens/shelter
- Barn
- Blacksmith
- Carriage house
- Cemetery
- Cotton gin house
- Crib
- Dairy
- Dam
- Delco generator
- Fence/Wall
- Garage
- Gazebo/Summerhouse
- Greenhouse
- Ice house
- Irrigation canal
- Jail
- Kitchen
- Kitchen with breezeway
- Office
- Original equipment/machine
- Other dwelling
- Oven
- Privy
- Raceway/Millrace
- Root cellar
- School
- Shed
- Silo
- Slave dwelling
- Smokehouse
- Stable
- Tenant house
- Tractor shed
- Well/spring house
- Windmill
- Other:

OUTBUILDING CONSTRUCTION: (Select 4)

- Unknown
- N/A
- Brick
- Frame
- Log
- Stone
- Other:

TOTAL NUMBER OF OUT BUILDINGS: _____

LANDSCAPE FEATURES: (Select up 4)

- Unknown
- N/A

[YARD SETTING]

- Casual/Unplanned
- Designed plantings/Flower beds
- Designed drives/walks
- Designed fencing/walls
- Formal/Geometric garden
- Informal/Picturesque
- Terracing/Contouring

[STREETSCAPES]

- Artwork/Monument
- Fountain
- Median strip
- Ornamental paving
- Planters
- Street furniture
- Town square/Courthouse square
- Trees/Landscaping

[RURAL LANDSCAPE]

- Drainage/Irrigation
- Fence/Hedgerows
- Field systems
- Pastures
- Pecan/Other groves/orchards
- Terracing/Contouring

[FOREST/WOODS]

- Natural
- Planted
- Other:

HISTORICAL INFORMATION

PERIOD OF CONSTRUCTION:

- Unknown
- N/A
- pre-1800
- 1801-1825
- 1826-1865
- 1866-1885
- 1886-1915
- 1916-1930
- 1931-1945
- post 1946

ACTUAL DATE OF CONSTRUCTION:

1848

ESTIMATED DATE OF CONSTRUCTION: c. _____

MAJOR ALTERATIONS:

FIRST: 1881
moved to its present site

SECOND:

THIRD:

HISTORICAL ASSOCIATION #1

PERSONS/EVENTS OF SIGNIFICANCE: _____

PERSON/EVENT/PATTERN:

- Unknown
- N/A
- Architect
- Traditional builder/craftsman
- Attributed builder
- Contractor
- Author of pattern book
- Landscape designer
- Original owner
- Later owner
- Historical significant person
- Historical significant event
- Historical significant broad pattern
- Historical significant government agency
- Other:

PERIOD OF SIGNIFICANCE:

- Unknown
- N/A
- pre-1800
- 1801-1825
- 1826-1865
- 1866-1885
- 1886-1915
- 1916-1930
- 1931-1945
- post 1946

ACTUAL DATE: _ _ _ _

SOURCE:

NOTES:

SIGNIFICANCE

LEVEL OF SIGNIFICANCE:

- Unknown
- N/A
- Local
- State
- National

AREAS OF SIGNIFICANCE: (3)

- Unknown
- N/A
- Agriculture
- Architecture
- Archeology
 - Prehistoric
 - Aboriginal
 - Non-Aboriginal
- Art
- Commerce
- Communications
- Community Planning
- Conservation
- Economics
- Education
- Engineering
- Entertainment/Recreation
- Ethnic - Asian
- Ethnic - Black
- Ethnic - European
- Ethnic - Hispanic
- Ethnic - Native American
- Ethnic - Pacific Islander
- Ethnic - other:
- Exploration/Settlement
- Health/Medicine
- Industry
- Invention
- Landscape Architecture
- Law
- Literature
- Maritime History
- Military
- Performing Arts
- Philosophy
- Politics/Government
- Religion
- Science
- Social History
- Transportation
- Other

CULTURAL AFFILIATION:

- Unknown
- N/A
- American Indian
- Black
- Caribbean
- Eastern European
- English
- French
- German
- Greek
- Iberian
- Irish
- Italian
- Oriental
- Other European
- Scandinavian
- Scotch Irish
- Scottish
- Southeast Asian
- Welsh
- Other:

STATE AFFILIATION:

- Unknown
- N/A
- Alabama
- Alaska
- Arizona
- Arkansas
- California
- Colorado
- Connecticut
- Delaware
- District of Columbia
- Florida
- Georgia
- Hawaii
- Idaho
- Illinois
- Indiana
- Iowa
- Kansas
- Kentucky
- Louisiana
- Maine
- Maryland
- Massachusetts
- Michigan
- Minnesota
- Mississippi

RELIGIOUS AFFILIATION:

- Unknown
- N/A
- AME Zion
- Baptist
- Catholic
- Christian Science
- Church of Christ
- Congregationalist
- Disciples of Christ
- Episcopalian
- Fundamentalist
- Greek Orthodox
- Jewish
- Lutheran
- Methodist
- Other Protestant
- Presbyterian
- Quaker
- Reformed Lutheran
- Other:

- Missouri
- Montana
- Nebraska
- Nevada
- New Hampshire
- New Jersey
- New Mexico
- New York
- North Carolina
- North Dakota
- Ohio
- Oklahoma
- Oregon
- Pennsylvania
- Rhode Island
- South Carolina
- South Dakota
- Tennessee
- Texas
- Utah
- Vermont
- Virginia
- Washington
- West Virginia
- Wisconsin
- Wyoming
- Other:

EVALUATION

SURVEYOR'S NAME: Stuart, James A.

DATE: / /

OFFICE EVALUATOR: _____

DATE: / /

NATIONAL REGISTER ELIGIBILITY:

- Unknown
- N/A
- Insufficient information
- Not evaluated
- Individual - Field determined
- Individual - Office determined
- Individual - NPS Determination of Eligibility
- Individual - NR listed
- District - Field determined
- District - Office determined
- District - NPS Determination of Eligibility
- District - NR listed
- Not eligible - age
- Not eligible - integrity
- Not eligible - significance
- Delisted
- Other:

NOTES:

ADDITIONAL DOCUMENTATION

Archaeological Site Number: ___ - ___ - ___
Alabama Register: NO ___ YES
National Historic Landmark: NO ___ YES
H.E.L.P.: NO ___ YES
FLOOR PLAN: ___ NO YES
MEASURED DRAWINGS: NO ___ YES
ELEVATION: NO ___ YES
SLIDES: ___ NO YES
HISTORIC PHOTOGRAPHS: NO ___ YES
SURVEY FILE: NO ___ YES

DESTROYED: NO ___ YES YEAR DESTROYED: ___ - ___ - ___

NATIONAL REGISTER: NO ___ YES YEAR LISTED: ___ - ___ - ___

TYPE OF LISTING:

- ___ Unknown
- ___ N/A
- ___ District
- ___ Individual

HISTORIC DISTRICT NAME: _____

MULTIPLE PROPERTY NAME: _____

TYPE NAME: _____

OWNERSHIP

OWNERSHIP GROUP:

- Unknown
- Private - Individual(s)
- Private - Non-profit organization
- Public - Local
- Public - State
- Public - Federal
- Public - Unknown
- Other:

OCCUPANCY:

- Unknown
- N/A
- Owner
- Tenant
- Vacant
- Other:

OWNER'S NAME/ADDRESS:

FIRST NAME: Ackerville Baptist Memorial Association LAST NAME: _____

MAILING ADDRESS: 4081 Larwood Drive

CITY: Mobile STATE: AL ZIP CODE: 36609

NOTES:

James A. Stuart is History
Committee Chairman; his
address is above